

EGR COOLER CONNECTOR TUBE

HEAVY DUTY REPLACEMENT FOR MACK MP7 & MP8 ENGINES

Wheeler Fleet Solutions EGR Cooler Connector Tube was engineered in response to a growing problem our customers had with constant failures of the Mack OEM EGR Tube. Our solution eliminates cracking or deformation in the seal area saving you costly hassle of constant downtime. Wheeler Fleet Solutions strives to provide problem parts solutions to keep your trucks on the road.

NOW THAT'S UPTIME DELIVERED!



OEM PROBLEM MACK P/N 21434720

- WEAK PLASTIC CONSTRUCTION
- HIGH TEMPERATURES DEFORMS AND CRACKS TUBE OVER TIME
- CONSTANT FAILURES REQUIRE SEVERAL HOURS OF MAINTENANCE JUST TO ACCESS THE EGR TUBE



AFTERMARKET SOLUTION WHEELER P/N 21434720MOD

- ANODIZED COATING FOR CORROSION RESISTANCE
- ELIMINATES CRACKING OR DEFORMING IN THE SEAL AREA COMPARED TO OEM
- HEAVY DUTY DESIGN NEVER NEEDS REPLACED AFTER INSTALL
- INCLUDED AFTERMARKET SEALS P/N 821071
- OEM SEALS P/N 1547253 ARE ALSO AVAILABLE INDIVIDUALLY

NEED MORE PARTS? WE'RE HERE TO HELP

wheelerfleet.com | 866.439.2329